The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

File Original and First Copy with Department of Ecology Second Copy — Owner's Copy 55258

WATER WELL REPORT

Start Card No. <u>W079677</u>

UNIQUE WELL I.D. #

Sec	and Cany Owner's Cony	VASHINGTON Water Right Permit No			
	OWNER: Name City of Moses Lake Add	ress321 South Balsam, Moses Lake,	WA 9	8837	
(2)	LOCATION OF WELL: County GRant	1/4 <u>SW</u> 1/4 Sec_ <u>1 4</u> T1	9 N., R	28_w.m.	
(2a)	STREET ADDRESS OF WELL (or nearest address) 324 5th Av	e, Moses Lake, WA 98837			
(3)	PROPOSED USE: Domestic Industrial Municipal	(10) WELL LOG OF ABANDONMENT PROCEDURE DESCRIPTION			
	□ DeWater Test Well □ Other □	Formation: Describe by color, character, size of material and structure, and s and the kind and nature of the material in each stratum penetrated, with at change of information.			
(4)	TYPE OF WORK: Owner's number of well (If more than one) #7	MATERIAL MATERIAL	FROM	то	
	Abandoned New well Method: Dug Bored Deepened Cable Driven Reconditioned Rotary Jetted	Perforated Existing 16" Casing	620	675	
(5)	DIMENSIONS: Diameter of well 14 inches. Drilled 0 feet. Depth of completed well 950 ft.	Installed 14" Casing to 685 Ft & Pressure Grouted with Neat Cement			
<u></u>	· · · · · · · · · · · · · · · · · · ·	THE STATE OF WILLIAM AND MEAN MEAN MEAN MEAN MEAN MEAN MEAN MEAN			
(6)	CONSTRUCTION DETAILS: Casing installed: 14 Diam. from 0 ft. to 685 ft. Weided Image: Construction of the construction of	Cleaned out Bentonite Plug	685	695	
	Welded	Cleaned out Pea Gravel Backfill	695	950	
	Perforations: Yes No \square Type of perforations 224 perforations from 620 ft. to 675 ft. perforations from 20 ft. to 675 ft.				
	perforations fromft. toft.				
	Screens: Yes No Manufacturer's Name				
	Type	1 1 101 3 1007	$\prod_{i=1}^{n}$		
	Diam. Slot size from ft. to ft.		U ;		
	Gravel placed from	DEPARTMENT OF ECOLOGIC	;Y		
	Surface seal: Yes No To what depth? 685 ft. Material used in seal Neat Cement - 29 Yds Did any strata contain unusable water? Yes No Type of water? Depth of strata Method of sealing strata off				
(7)	PUMP: Manufacturer's Name				
(B)	WATER LEVELS: Land-surface elevation above mean sea level ft.	Work Started Oct 11,96, 19. Completed NOV	20	19 <u>96</u>	
	Artesian water is controlled by (Cap, valve, etc.)	WELL CONSTRUCTOR CERTIFICATION: I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and			
(9)	WELL TESTS: Drawdown is amount water level is lowered below static level Was a pump test made? Yes No If yes, by whom?	the information reported above are true to my best knowledge and belief. NAME Irrigators. Inc.			
	Yield:gal./min. withft. drawdown afterhrs.	n after hrs. (PERION, FIRM, OR CORPOSATION) (TYPE OR PRINT)			
	Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level) Time Water Level Time Water Level Time Water Level	Address P. O. Rifx 44 MOSes Lake, WA 98837 (Signed) WELL BY SERIE No. 1064			
<u> </u>		Contractor's Registration No. IRRIGI*1160J Date NOvember	10,	, 19 <u>97</u>	
_	Date of test	(USE ADDITIONAL SHEETS IF NECESSARY)			
	Bailer testgal./min. withft. drawdown after hrs. Airtestgal./min. with stem set atft. for hrs.	Ecology is an Equal Opportunity and Affirmative Action e			

